

HEALTH AND SAFETY REPORT

Regulatory Services, P.O.BOX 634, Barnsley, S70 9GG

Continuation Sheet

Listed below are the findings of the inspecting officer and a timescale for completion of these actions. Legal requirements must be carried out to comply with health and safety law. Actions marked R are not specifically required by law but are advice on good practice to reduce risk. ACTION LIST If you wish to carry out alternative remedial action please discuss this with the officer Repair the hard surface to the yard area to remove tripping hazards and to ensure effective drainage Require the rainwater pipe to the wall (above smoking shelter) Make good all holes in the external structure of the building such that no brick or masonry can fall or cause injury Permanently highlight all changes in level in public areas throughout the premises Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping Secure all beer gas cylinders upright (full, empty and in use) Do not allow smoking under the covered archway Permanenting (Prohibition Notice SRB/SUGARCLUB/22/1 pending) Refore access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. Repair the external beer drop hatch and then maintain it in good repair and efficient working order	Business Name					
actions. Legal requirements must be carried out to comply with health and safety law. Actions marked R are not specifically required by law but are advice on good practice to reduce risk. ACTION LIST If you wish to carry out alternative remedial action please discuss this with the officer hazards and to ensure effective drainage Repair the hard surface to the yard area to remove tripping hazards and to ensure effective drainage Recurrently repair all of the wall (above smoking shelter) Make good all holes in the external structure of the building such that no brick or masonry can fall or cause injury Permanently highlight all changes in level in public areas throughout the premises Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping Secure all beer gas cylinders upright (full, empty and in use) Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. Secured the rainwater pipe to the wall (above smoking shelter) Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions.	REQUIREMENTS & RECOMMENDATIONS TO IMPROVE HEALTH & SAFETY					
Repair the hard surface to the yard area to remove tripping hazards and to ensure effective drainage 7 Secure the rainwater pipe to the wall (above smoking shelter) 8 Make good all holes in the external structure of the building such that no brick or masonry can fall or cause injury 9 Permanently highlight all changes in level in public areas throughout the premises 10 Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping 11 Secure all beer gas cylinders upright (full, empty and in use) 12 Do not allow smoking under the covered archway 13 Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 10 30/5/22	actions. Legal requirements must be carried out to comply with health and safety law. Actions			pens	n pleted e)	
hazards and to ensure effective drainage 7 Secure the rainwater pipe to the wall (above smoking shelter) 8 Make good all holes in the external structure of the building such that no brick or masonry can fall or cause injury 9 Permanently highlight all changes in level in public areas throughout the premises 10 Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping 11 Secure all beer gas cylinders upright (full, empty and in use) 12 Do not allow smoking under the covered archway 13 Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 1 30/5/22 30/5/22	Number		Legal Stand Required (see Codes	Guidance Is	To be con by (Dat	
throughout the premises 1 Permanently rightight all changes in level in public areas 1 throughout the premises 1 Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping 1 Secure all beer gas cylinders upright (full, empty and in use) 5 5/5/22 12 Do not allow smoking under the covered archway 21 Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 1 30/5/22	6	,	12	www.hse.gov.uk	30/5/22	
throughout the premises 1 Permanently rightight all changes in level in public areas 1 throughout the premises 1 Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping 1 Secure all beer gas cylinders upright (full, empty and in use) 5 5/5/22 12 Do not allow smoking under the covered archway 21 Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 1 30/5/22	7	Secure the rainwater pipe to the wall (above smoking shelter)	1		30/5/55	
throughout the premises 1 Permanently rightight all changes in level in public areas 1 throughout the premises 1 Permanently repair all damaged internal floor surfaces and floor coverings to prevent persons tripping 1 Secure all beer gas cylinders upright (full, empty and in use) 5 5/5/22 12 Do not allow smoking under the covered archway 21 Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 1 30/5/22	8	· · ·	12		30/5/22	
floor coverings to prevent persons tripping 11 Secure all beer gas cylinders upright (full, empty and in use) 12 Do not allow smoking under the covered archway 13 Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 5 5/5/22 5/5/22 Before access to cellar 30/6/22 30/6/22	9		1		30/5/22	
12 Do not allow smoking under the covered archway 13 Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1 metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 5 5/5/22 5/5/22 Before access to cellar all access to cellar staircase and obtain approved to the access to cellar access to access to cellar access	10	· ·	1		30/5/22	
Devise a system for safe access to the cellar area and obtain approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 5	11	Secure all beer gas cylinders upright (full, empty and in use)	5		5/5/22	
approval in writing from BMBC Regulatory Services before implementing (Prohibition Notice SRB/SUGARCLUB/22/1 pending) 14 Securely fence the opening created by the open cellar hatch inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 18 access to cellar 30/6/22 30/5/22	12	Do not allow smoking under the covered archway	21		5/5/22	
inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1metre before the start of the staircase. 15 Provide and fix a handrail to the cellar staircase and clear all floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 5 30/5/22	13	approval in writing from BMBC Regulatory Services before implementing	1		access to	
floors and walkways of materials and obstructions. 16 Repair the external beer drop hatch and then maintain it in 5 30/5/22	14	inside the premises by means of a stud partition wall with a numbered keypad protected doorway 1metre before the start	12		30/6/22	
	15		12		30/5/22	
	16	·	5		30/5/22	

Please sign to acknowledge receipt of these reports and the guidance leaflets indicated.

Officer's Signature Stephen Butler

Recipient's Signature By email to ashleystockton81@icloud.com